



# PAC BULLETIN SERVICE



October 29, 2018

Subject: **New Drive Belt P/N 417300571**

No. **2019-7**

YEAR	MODEL
2017-2018-2019	Models with 850 E-TEC engine

## PRODUCT IMPROVEMENT

As part of BRP's continuous product improvement strategy, a new drive belt is available.

DESCRIPTION	PART NUMBER
Drive Belt	417300571

## RIDING STYLES AND CONDITIONS

The new drive belt is an alternative to the 417300531, with new material and construction offering increased durability for 850 E-TEC Gen4 Summit™ and Freeride™ customers who ride in the following conditions:

- Specific snow conditions such as deep powdered snow or deep heavy snow
- Use the 850 E-TEC engine at its peak power range
- Have highly dynamic, intense, or energetic riding styles.

## BENEFITS

The greatest benefits of this new drive belt will be noticed on:

- Model year 2019 850 E-TEC Gen4 Summit and Freeride models
- Model year 2017 and 2018 850 E-TEC Gen4 Summit and Freeride models having the engine mount updates as per warranty bulletin *SKI-DOO 2018-10* Drive Belt Durability or service bulletin *SKI-DOO 2018-8* Maximizing Drive Belt Life improvements performed.

The 417300571 durability performance is expected to be similar or better than the 417300531 on other trail and crossover Ski-Doo™ models, depending on riding styles and conditions.

## AVAILABILITY

Limited quantity available for the beginning of the season.

- Selective release will be applied on orders until quantities have stabilized. This is to ensure even network distribution of the new belt.
- Due to selective release, it is normal to get a message indicating “No Availability at the Present Time”.